



Topic: Material changeover due to global supply shortages

Dear Sir or Madam,

the following product of our product range will be changed.

Article number	Description	Category of change	Description of change	Launch date
1.10.031.xxx/xxxx	RAMO 22 E	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
1.11.031.xxx/xxxx	RAMO 30 E	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
1.15.154.xxx/xxxx	LUMOTAST 25 emergency stop pushbutton	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
1.30.240.xxx/xxxx	RAFIX 22 QR pushbutton	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover front ring and pressure piece due to global supply shortages	July 2021
1.30.242.xxx/xxxx	RAFIX 22 QR selector switch	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover front ring due to global supply shortages	July 2021



Publication date: July 12, 2021

1.30.243.xxx/xxxx	RAFIX 22 QR emergency stop	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover front ring due to global supply shortages	July 2021
1.30.245.xxx/xxxx	RAFIX 22 QR keylock switch	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover front ring due to global supply shortages	July 2021
1.30.246.xxx/xxxx	RAFIX 22 QR mushroom-headed pushbutton	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom button due to global supply shortages	July 2021
1.30.250.xxx/xxxx	RAFIX 22 FS pushbutton	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover pressure piece due to global supply shortages	July 2021
1.30.253.xxx/xxxx	RAFIX 22 FS emergency stop	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
1.30.255.xxx/xxxx	RAFIX 22 FS+ keylock switch	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover front ring due to global supply shortages	July 2021



Publication date: July 12, 2021

1.30.273.xxx/xxxx	RAFIX 22 FS+ emergency stop	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
1.30.283.xxx/xxxx	RAFIX 22 FSR emergency stop	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
9.10.031.xxx/xxxx	RAMO 22 E	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
9.11.031.xxx/xxxx	RAMO 30 E	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
9.15.154.006/0300	EMERGENCY STOP PUSHBUTTON LUMOTAST 25 TH	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom button due to global supply shortages	July 2021
9.30.240.xxx/xxxx	RAFIX 22 QR pushbutton	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover pressure piece due to global supply shortages	July 2021



Publication date: July 12, 2021

9.30.242.xxx/xxxx	RAFIX 22 QR selector switch	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover front ring due to global supply shortages	July 2021
9.30.243.xxx/xxxx	RAFIX 22 QR emergency stop	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
9.30.246.xxx/xxxx	RAFIX 22 QR mushroom-headed pushbutton	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom button due to global supply shortages	July 2021
9.30.253.xxx/xxxx	RAFIX22 FS emergency stop	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
9.30.273.xxx/xxxx	RAFIX 22 FS+ emergency stop	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021
9.30.283.001/0000	RAFIX 22 FSR emergency stop	☐ dimensional☒ appearance☒ materials☐ functional☐ other	Material changeover mushroom head due to global supply shortages	July 2021



Publication date: July 12, 2021


You may already be aware that the global market situation for certain raw materials and primary products is extremely tight at present. Numerous manufacturers with increasing demands are only being supplied with delivery quantities below market requirements.

RAFI has also been severely affected in the meantime for various products. Particularly due to the shortage of plastic granulates, our material demands cannot be completely met by our suppliers.

We would like to inform you that the ability to deliver our products has a very high priority for us. Due to this, we are forced to switch to an alternative plastic material for some individual parts of our products in order to counteract an impending inability to deliver.

We are willing to accept the high internal effort of material conversion and testing and continue to deliver a consistently high quality. In addition, all designated approvals remain valid, as we use approved alternative materials. However, it is unfortunately unavoidable that slight color differences may occur in individual cases.

This is exemplified by the following image comparison, in which the red material of the mushroom head has been converted:





Publication date: July 12, 2021

We hope for your understanding for this extraordinary situation and your confidence in our products and are looking forward to our further cooperation.

If you have any further questions, please do not hesitate to contact us. Please contact the person you know. You can also find all information about our components in our RAFI eCatalog: https://components.rafi.de

Best regards,

Product Management